## STATE OF CONNECTICUT

CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford, Connecticut 06106 (203) 566-3005

## HISTORIC RESOURCES INVENTORY FORM

For Buildings and Structures

TOWN NO.:		SI'	TE NO.:
UTM: 18/_	//_	/_	-//
QUAD:		· ' .	
DISTRICT:	\$	NR:	ACTUAL

IDENTIFICATION	*,*,		
1. BUILDING NAME: Common: Har	riet Cooper Lane House	Historic: Robert Sm	ithson House
2. TOWN/CITY: Middletown	VILLAGE: West Long	Hill COUNTY: Mi	ddlesex
3. STREET & NUMBER (and/or locati	on): 30 Laurel Grove	Road	
4. OWNER(S): George Mylchree	st	PL	BLIC X PRIVATE
5. USE: Present: Residence	Histor	ic: same	
6. ACCESSIBILITY TO PUBLIC: Exte			
inter	rior accessible: $\underline{\mathbf{x}}$ yes, explain	with owner's perm	1SSION NO
DESCRIPTION			
7. STYLE OF BUILDING: Center-	Chimney Colonial [	DATE OF CONSTRUCTION	1: 1741
board & batten		brick fieldstone cobblestone x cut stone: type:	er sign on house)  brownstone  foundation
9. STRUCTURAL SYSTEM:  _x_wood frame:x_post and beam load bearing masonryother:	_balloon structural iron or steel		seen above grade)
10. ROOF: type: x gableflatgambrelshed material:x wood shingleroll asphalt	mansard monitor hip round tin slate	sawtooth other	
asphalt shinglebuilt up	tile other:	23'x39'; ad	dition and
11. NUMBER OF STORIES: 2½	APPROXIMATE DIM	ENSIONS: garage 30'x	40 1
			deteriorated deteriorated
13. INTEGRITY: Location:on originalon _xye	al site x moved, when: 19 es, explain: <u>Chimney repl</u>		
14. RELATED OUTBUILDINGS OR LAbarnshedxcarriage houseshop	garage sother la	ndscape features or building	\$:
15. SURROUNDING ENVIRONMENT: open landwoodland _xcommercialindustrial _x	residentialscattere ruralhigh bu	d buildings visible from site Iding density	,
16. INTERRELATIONSHIP OF BUILDI faces west from the east side of It is set back behind a yard wit	Laurel Grove Road nea	r the intersection of	Wadsworth Street

the street is the Nehemiah Hubbard House (c. 1730). Laurel Grove Road is an unpaved lane

with tall trees shading scattered residences.

## 17. OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior):

Entrance porch Triple-run staircase

SIGNIFICANCE Architect:	Builder:		
18. HISTORICAL OR ARCHITECTURAL IMPORTAN Street of Durham, Connecticut near the site was probably built around 1741 by Robert Sm site. It is remembered in Durham as the Ha former occupant. This house displays the center-chimney, t century house construction. In its well-pr Hubbard House across the street. Together Laurel Grove Road a pleasing streetscape re	ICE: This house of of the Durham Mithson. In 1957 rriet Cooper Lan wo-room deep placeserved condition these two houses	anufacturing Con it was moved to e House after a n typical of mid n it complements make the entra	mpany. It o its present long-term d-eighteenth- s the Nehemiah nce into
PHOTOGRAPH			
photographer: Roger Sherman		4.57	
date: 9/78 view: West		en e	
negative on file: Roll 42, #24A		Ji.	
COMPILED BY:  name: John E. Reynolds date: organization: Greater Middletown Preservation address: 27 Washington St., Middletown, Ct.	Trust		
19. SOURCES: Interview with present owner 3/ interview with Mrs. Frances E. Korn of Durha Connecticut.			
20. SUBSEQUENT FIELD EVALUATIONS:			
			$(x,y) = (x,y) + \frac{y}{y} $
A4 TUDE : TO TO DUM DIMO OD CITE			•
21. THREATS TO BUILDING OR SITE:	davalanara	_ other:	•
_x_none knownhighways vandalism renewalprivate deterioration		explanation:	· · · · · · · · · · · · · · · · · · ·
tellewasprivatedeterioration	ZVIIII8	_ vapidiidiiviii	